Illinois Commerce Commission Pipeline Safety

Exit Meeting Documentation Form

| Operator: | AMEREN ILLINOIS COMPANY |
|--------------------------|-------------------------|
| Inspection Unit(s): | Petersburg |
| Date of Meeting: | 11/05/2015 |
| Pipeline Safety Analyst: | Kevin Hecker |
| Exit Meeting Contact: | Keith Hinrichs |

Exit Statement

INSPECTION FINDINGS

Standard Inspection - Field Audit

Issues(s) Found:

Code Part [192.353(a)] - The AC unit coolant line was installed through the meter set. The coolant line and thermostat wire is in contact with the meter set.

Code Part [192.355(b)(2)] - An intake/exhaust vent is directly over the regulator vent at 117 Antle, Petersburg.

Code Part [192.355(b)(2)] - An intake/exhaust vent to the house is directly above the regulator vent at 403 10th Street, Petersburg.

Notice Of Amendment(s) Found:

[NO NOAS FOUND]

Notice Of Violation(s) Found:

[NO NOPVS FOUND]

Standard Inspection - Record Audit

Issues(s) Found:

[NO ISSUES FOUND]

Notice Of Amendment(s) Found:

[NO NOAS FOUND]

Notice Of Violation(s) Found:

[NO NOPVS FOUND]

PAST INSPECTION FINDINGS

Issue(s) Corrected:

[NO ISSUES CORRECTED]

Notice Of Amendment(s) Corrected:

[NO NOAS CORRECTED]

Notice of Violations(s) Corrected:

[NO NOPVS CORRECTED]

Pipeline Safety Analyst Signature:

Kerin Kreker_

Operator Representative Signature:

Keth R Warts